

October 11, 2021

Proprietary Magnet Inspection Aid for SPIN EZ® Oil Filters No Longer Available

The Tempest® SPIN EZ® spin-on oil filters' FAA approved design includes an optional magnetic inspection aid for maintenance personnel which is capable of attracting fine steel particles to assist with detecting ferrous material during post oil-change filter inspection.

Unfortunately, due to supply chain disruptions, we are currently unable to procure this proprietary magnet and therefore unable to continue offering this additional feature. All other components and filtration quality you trust from Tempest® SPIN EZ® spin-on oil filters remain unchanged.

For questions or additional information on this or other Tempest Aero Group[®] products, please contact support@tempestaero.com or (336) 449-5054. Additional information on Tempest Aero Group and its affiliate companies can also be found at www.tempestaero.com.

Effective immediately, oil filters will be shipped without magnets. The beginning date code for each oil filter is shown below:	
Part Number	Date Code
AA48103-2	5L and beyond
AA48104	5J and beyond
AA48108-2	5O and beyond
AA48109	5N and beyond
AA48110-2	5C and beyond
AA48111	5k and beyond