

Carburetor to Engine Gaskets


FAA-PMA Approved Continental and Lycoming Engine gaskets

**In stock,
ready to ship!**

NEW



P/N 652105
P/N 652137



P/N SL60592
P/N SL66224

Engine Models	P/N	Location
Continental Series		
E-165,185,225	652137	Carburetor to Engine
O-470		
IO-470		
TSIO-360		
LTSIO-360		
A65, A75	652105	Carburetor to Engine
C125-2, C145-2,2H, C75, C85, C90		
O-200-A,B		
O-300-A,B,C,D		
Lycoming Series		
O-320, IO-320, AEIO-320, AIO-320, LIO-320,O-320-H	SL66224	Carburetor or Fuel Injector to Engine
O-340		
O-360, HO-360, IO-360, HIO-360, AIO-360, TIO-360, VO-360, IVO-360, LO-360 E1A6D, TO-360, LTO-360		
VO-435, TVO-435		
GO-480		
O-540, IO-540, TIO-540, VO-540, TIVO-540		
O-235-C1,B,C, C2A,C, F2A,B, H2C, J2A, K2A,B,C, L2A,C, M1, N2A,C, P2A		
O-290-D,D2,D2B,D2C	SL60592	Carburetor to Engine

Manufactured by Superior Air Parts, Inc.

Exhaust to Engine Cylinder Gaskets

FAA-PMA approved Continental and Lycoming Gaskets

- Blow-proof gaskets
- Save money now, and down the road!

NEW



P/N RA77611



P/N RA970



P/N RA628620

Manufactured by Superior RAPCO, Inc.

Continental Engine Model	Description	Part Number		
A-65, A-75	Gasket, Engine Exhaust, Solid Gasket, Engine Exhaust, Spiral Wound	RA632837 RA627429		
C85-12F				
C90-8F,12F,14F,16F				
E-165, E-185, E-225				
O-200-A,B				
O-300-A,C,D				
O-470-A,E,J				
TSIO-520-A,B,C,D,E,G,H,J,K,L,M,N,P,R,T,U	Gasket, Turbocharger Wastegate	RA636465		
TSIO-520-AE,AF,BB,BE,CE,DB,EB,JB,KB,LB,NB,UB,VB,WB				
LTSIO-520-AE	Gasket, Engine Exhaust, Spiral Wound	RA628260		
IO-360-A				
O-470-B,G,K,L,M,P,R,S,U,IO-470-D,U,V, TSIO-470-B				
GTSIO-520-C, TSIO-520-B,C,D				
IO-360-A,C,D	Gasket, Engine Exhaust, Spiral Wound	RA970		
TSIO-360-A,B				
Lycoming Engine Model				
O-340	Gasket, Engine Exhaust, Spiral Wound	RA77611		
O-360, HO360-B, IO-360-A,B,C, HIO-360-A,B,C				
O-540-A,B,E,G,J,K, IGO-540-A, IGSO-540-A				
IO-320				
IO-720-A				
GO-480, GSO-480				
VO-435, TVO-435				
ISGO-430				
E1A4, E1B4, E1C4, TIO-541, TIO-541-A1A			Gasket, Engine Exhaust, Spiral Wound	RALW15486
			Gasket, Engine Exhaust, Solid	RALW15619



Airbox to Carburetor Gaskets

FAA-PMA approved!

- We have them in stock, ready for you!
- Eligible for Cessna and Piper Aircraft
- Drastic savings!
- MIL-SPEC Fuel Proof



P/N MC73451-07



P/N MC649974



P/N MC63684-04



P/N MC0750142-1



P/N MC2050005-1

Aircraft Models	Part Number
Cessna	
172I,K,L,172M ¹ ,N,P, F172L,F172M ¹	MC649974
172Q	MC0750142-1
172R,S	MC2050005-1
175, 175A,B,C	MC0750142-1
180 ² , 180A,B,C,D,E,F,G,H,180J ² ,K	
182, 182A,B,C,D	
188, 188A,B	
Piper	
PA-28-140, PA-28-150, PA-28-151, PA-28-160, PA-28-161 ³	MC73451-07
PA-28-180, PA-28R-180, PA-28-181 ⁴	MC63684-04
PA-28R-200, PA-28R-201 ⁵ , PA28RT-201	
PA-28-235	
PA-28-236 ⁶	

Notes:

- 1 172M S/N 17260759 thru 17267584; F172M S/N F17200905 thru F17201234
- 2 180 S/N 32151 thru 32661; 180J s/n 18052285 thru 18052770
- 3 PA-28-161 S/N 28-7716001 thru 28-8616057; 2816001 thru 2816119; 2841001 thru 2841365 2842001 thru 2842999
- 4 PA-28-181 S/N 28-7690001 thru 28-8690062, 2890001 thru 2890231, 2843001 thru 2843999
- 5 PA-28R-201 S/N 28R-7737002 thru 28R-7837317, 2837001 thru 2837061, 2844001 thru 2844999
- 6 PA-28-236 S/N 28-7911001 thru 28-8611008, 2811001 thru 2811050

Avglas™ STC Repair Kit for Continental Steel Carburetor Heat Boxes

New hardened stainless steel bearing for vibration resistance and longer life!

FAA-PMA, STC Kits include:

- Replacement shaft, arm, and detent spring assembly
- Bearings
- Bearing housing
- Locknut and washer
- Complete instructions



P/N FG-105

Installation:

The butterfly (not included in kit) must be brazed or tack welded to the shaft during installation. The bearing housings must be brazed, tack welded, or flush riveted to the carburetor heat box. Avoid applying excessive heat during brazing or tack welding, or the heat-treated stainless steel bearing may be damaged.



P/N FG-SK-1

Engine Model	Continental Airbox P/N	Avglas P/N
C-75	50256	FG-100
C-85	50256	FG-100
C-90	50256	FG-100
O-200	628122, 653675, 641534	FG-100
O-300	530852, 531143	FG-105

Spring Service Kit P/N FG-SK-1

Eligible for installation on P/N FG-100 and FG-105.

Service kit contains (1) FG102S Spring and (2) MS20613-3-P3 Rivets

Avglas repair kits only applicable to aircraft.